DAILY WORK	
Work Site: Bossert Manufacturing	Work Period: 8/21/87
,	OSC: Jack D. Harmon
WORK PLANNED/AUTHORIZED: 1.)Continue to clean out sumps #13 & #14 and begin #16, #17 & #18 2.)Fine tune water treatment system and send processed water back to 50K pool 3.)Check into disposal of drums, PCB oil in 12K pool, PCB oil in drums, and clean oil in drums 4.)Shovel sludge out of the drying bed/smooth out sand. 5.)Repair small laser (3000 PSI) laser packing. 5.)Check vats for leaks then fill with 50K oil. 7.)Sample areas #10, #11 (2nd Floor),	WORK ACCOMPLISHED FROM PREVIOUS WORK ORDER: Yes No Continues 1.) (x) () () 2.) (x) () (x) 3.) () () (x) 4.) () (x) () 5.) () (x) () COMMENTS: Sump #47 debris will be cleared when crew returns to area #13. 7 ERCS personnel are
and begin 1st floor sampling. EQUIPMENT PLANNED/AUTHORIZED: (1) Vans (1) Pick-up Truck (1) Decon trailer (3) Bobcats (1) Command Post Trailer (1) Crew Trailer (3) 12K Pools (1) Portable Eye Wash (3) Car (6) Radioes (1) 50K Pool (1) Water Treatment System	weekend.
<pre>w/ appurtenances (2) High-Pressure Water Laser w/hoses (1) Mini-Trackhoe 20) Propane tanks (1) Cascade System (1) 6-CY Dumpster (1) 3-in (4) Submersible Pumps: (3) 2-in (3) Satelites (2) 6.5KW Generators</pre>	427710 WWW WWW (4) Porta-Johns (1) Pneumatic Forklift
(1) Response Manager (0) Laborer	(1) Foreman (3) (2) Foreman (2) (1) Field Clerk (3) Clean-up Technician (2)
Contractor Signature:	OSC Signature: